Plant Site 1 Groundwater Management Area NAPL Monitoring Report for Fall 2005

Table of Contents

Volume I of II

α	4	7	r		1		. •		
Section			n	tro	а	110	٠tı	\cap	n
OCCUOII		_	ш	LI ()	u	шv	ı.ı	ι,	11

Section 2 – Background Information

Section 3 – Historical NAPL Monitoring and Recovery Activities

Section 4 – Fall 2005 NAPL Monitoring and Recovery Results

Section 5 – Effectiveness Evaluation and Future Program Modifications

Section 6 – Schedule for Future Activities

Tables

Figures

Volume II of II

Appendices

A	Automated	Recovery	/ S	vstem	Constr	uction	Detail	S
---	-----------	----------	-----	-------	--------	--------	--------	---

- B Summary of Historical NAPL Recovery
- C Summary of Automated LNAPL Recovery
- D Summary of Automated DNAPL Recovery
- E Groundwater Elevation and NAPL Thickness/Recovery Data
- F East Street Area 2-South LNAPL Recovery Efficiency Data
- G River Bank Inspection Forms